



FIG. 15—2. Flow diagram depicting the principal units and auxiliaries in a modern blast-furnace plant, and showing the steps in the manufacture of pig iron from receipt of raw materials to disposal of pig iron and slag, as well as the methods for utilizing the furnace gases.